

REPORT of SURVEY for REPAIRS.

PA

No. _____ Port of London Date June 2nd 1835
 Survey of the Schooner Swallow Master Artis
 Tonnage 116 By whom built _____ Where built Gibraltar
 When built 1824 Owners Baylis & Co. Port belonging to London
 Destined Voyage _____
 Surveyed Afloat or in Dry Dock On the ways

Original Survey, No. ~~1174~~ Dated Feb^y 1835 A. 1
 Port London 1174

Repairs. Copper repaired — Rigging down and overhauled

General Observations and Opinion, as required by the Instructions } The Copper is now in an efficient state of Repair — The Hull and materials are in good condition
George Bayley

The Amount of Fee.....£ : : no fee is received by me.

Committee Minute 19 June 1835
 Character assigned Continue Class
J. M. H.