

REPORT of SURVEY for REPAIRS.

16/1.
JH

No. _____ Port of London Date July 25 1835
 Survey of the Britannia Master Gexton late Holmes
 Tonnage 190 By whom built _____ Where built Bideford
 When built 1810 Owners Crozier Port belonging to London
 Destined Voyage Mediterranean
 Surveyed Afloat or in Dry Dock On the ship

Original Survey, No. 594 Dated Sept^r 1834 Claper F. S.
 Port London

Repairs. Copper repaired

General Observations
and Opinion, as
required by the
Instructions.

The copper is in an efficient state of repair
 is well
 Hull is in good order and found in all the
 needful stores & materials

3 BA - 4 Topsails &c

George Bayley

The Amount of Fee..... £ Profee : is received by me.

Committee Minute 21 August 1835

Character assigned

Continue the class
MS



© 2021

Lloyd's Register
Foundation