

REPORT of SURVEY for REPAIRS.

No. 1771 Port of London Date Sept^r 7th 1835
549 Survey of the Barque John Pirie Master Matthews
 Tonnage 279 By whom built _____ Where built Sunderland
 When built 1828 Owners Cotton & Co Port belonging to London
 Destined Voyage Trinidad
 Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 957 Dated September 23rd 1834 Classed 10A1
 Port London

Repairs. At the present time has had a black African Oak Shelf
 worked under the Upper Deck and well secured.
 The waterway & 2 seams of the Deck caulked.

General Observations
 and Opinion, as
 required by the
 Instructions

This vessel is built with an half Poop - is not
 very well secured, the beam and has moved to a
 small extent. In other respects she is in
 good condition and presents a firm appearance.

George Bayley

27 If the ought to be charged.

The Amount of Fee.....2 No fee is received by me.

Committee Minute 18 Sept 1835

Character assigned

Continue class
GHD



© 2019

Lloyd's Register
 Foundation

LON 598-0074