

1000

REPORT of SURVEY for REPAIRS.

RA

No. 1808 Port of London Date Sept^r 29th 1835
 605
 Survey of the Bark Puckers Master J. Lopez
 Tonnage 269 By whom built _____ Where built London
 When built 1829 Owners Lopez Port belonging to London
 Destined Voyage Grenada
 Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 988 Dated Sept^r 29th 1834 Clapnet RA
 Port London

Repairs. *At the present time Copper repaired, Wash Boards and Gallies off and caulked behind - New topped Pintle to the Hudder*

General Observations and Opinion, as required by the Instructions *The copper is in an efficient state of repair - the condition of the ship is good throughout, no appearance of movement or overstrain. Masts, Rigging, Sails and other stores in good conditions*
George Bayley

The Amount of Fee.....*2* *shillings* is received by me.

Committee Minute 2 Oct^r 1835

Character assigned Continue Clap
G. M. D.

