

1811  
**REPORT of SURVEY for REPAIRS.** *ShA*

No. <sup>1811</sup> ~~1811~~ Port of *London* Date *Sept<sup>r</sup> 22<sup>nd</sup> 1835*  
<sup>1019</sup> Survey of the *Ship Symmetry* Master *Graves*  
Tonnage *382* By whom built *Tindalls* Where built *Scarbro'*  
When built *1823* Owners *Wm Tindale* Port belonging to *London*  
Destined Voyage \_\_\_\_\_  
Surveyed Afloat or in Dry Dock *Dry Dock*

Original Survey, No. *233* Dated *July 22<sup>nd</sup> 1834* Clased *F. 1*  
Port *London*

Repairs. *At the present time Docked & Copper examined.*

General Observations  
and Opinion, as  
required by the  
Instructions.

*The Copper and Upper Works of this Vessel are in  
good and efficient condition*

*George Bayley*

The Amount of Fee ..... *2* No fee: is received by me.

Committee Minute *2 Oct* 183 *5*

Character assigned

*Continue Class*

*no lying in City Canal*



© 2019

Lloyd's Register  
Foundation

LON 598-0115