

# REPORT of SURVEY for REPAIRS.

2053

No. 201 Port of London Date Oct 14 1835  
 Survey of the Barque Gilbert Monro Master C. Duff  
 Tonnage 258 By whom built \_\_\_\_\_ Where built Shields  
 When built 1828 Owners J. Hindley Port belonging to London  
 Destined Voyage Boundaries of the Mauritius  
 Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 760 Dated May 1834 Classed 10A1  
 Port London

**Repairs.** *At the present time has been caulked from the keel to the wale and coppered upon paper with 28.26.2403*

General Observations  
and Opinion, as  
required by the  
Instructions.

*The Wales Exposed, Planks, keels & Waterways of this Vessel are firm and in good condition she does not appear to have moved upon her fastenings or worked at her Beam Ends Her Hold & the Trunks are remarkably dry and in good condition - Sails, Shunts, Jards, Anchors, Cables & Boats are all in good and efficient condition*

*George Bayley*

The Amount of Fee ..... £ 1 : 1 : 0 is received by me. *[Signature]*

Committee Minute 22 Decmbr 1835

Character assigned Recor Coppering & continue Class 10A1  
*[Signature]*



© 2019

Lloyd's Register  
Foundation

LON 598-0389