

1004

No. 275 Survey held at London Date Jan 8 1836
on the Brig Belia Master Broughton
Tonnage 208 Built at Boston When built 1825
By whom built _____ Owners Capt. & Co
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 774 Port of London 1834 Classed 1041

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame } <u>Good</u>	Masts, Yards, &c. }
Decking	Topsides	Sails } <u>Good</u>
Deck Shears	Wales } <u>Two Planks shifted at present time</u>	Cables }
Overways	Plank & Treenails (Outside to the Water's Edge)	Anchors
Stowage Comings	Rudder } <u>Good</u>	Standing & Running Rigging
	Windlass	

General Observations and Opinion,
as required by the Instructions,

*This vessel has at the present time had two planks
of the lower edge of wale shifted - she should in my
opinion remain in her present class - but requires watching*

Committee Minute

15 January 1836

Inspector assigned

Continue Class 10 & 1

J. W. L.

George Bayley