

ANNUAL SURVEYS.

2393

No. 2393 Survey held at London Date April 14th 1836
 on the Ship Resolution Master J Gardner
 Tonnage 393 Built at Yarmouth When built 1800
 By whom built _____ Owners A Donett & Co.
 Port belonging to London Destined Voyage Dublin
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1438 Port of London Classed "E. 1"

The Surveyor is required to state the present Condition of the

Decks <u>In fair condition</u>	Breasthooks _____	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>ditto</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>ditto</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>ditto</u>	Topsides _____	Sails <u>Two sets</u>
Plank Shears <u>ditto</u>	Wales _____	Cables <u>Well found</u>
Waterways <u>ditto</u>	Plank and Treenails (Outside to the Water's Edge) _____	Anchors <u>ditto</u>
Hatchway Comings <u>ditto</u>	Rudder _____	Standing & Running Rigging <u>Good</u>
	Windlass _____	

General Observations and Opinion, At the present time two new decks beams thirteen new lodging & hanging knees, part new deck spirkettling & plank sheers, new rudder case, holdbeam refastened, three new planks in the topsides and partially caulked, is now in very good condition & I am of opinion may remain in her present class
 as required by the Instructions,

Committee Minute 19 April 1836

Character assigned Continued Class E. 1 W Middleton

No. 322 Survey held at London Date April 18th 1836
 on the By Onothena Master J Craig
 Tonnage 221 Built at Wexham When built 1826
 By whom built _____ Owners A Milne & Co.
 Port belonging to London Destined Voyage Grenada
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 597 Port of London 1834 Classed 10 A

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling _____	Topsides _____	Sails <u>Well found</u>
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank & Treenails (Outside to the Water's Edge) _____	Anchors _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging <u>Good</u>
	Windlass _____	

General Observations and Opinion, In very good condition no appearance of working or decay and may continue her present class
 as required by the Instructions,

Committee Minute 19 April 1836

Character assigned Continued Class 10 A W Middleton