

REPORT of SURVEY for REPAIRS.

No. 2645 Survey held at London Date July 8 1836
on the Ship Eden Master _____
Tonnage 513 Built at London When built 1826
By whom built Hutchinson & Co Owners J. Jones
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Messrs Hutchinson Dry Dock

Original Survey, No. 1003 Dated 1834 Class 12A1
Port London

Repairs. *At the present time caulked from the keel up
and recooped - Topsides scraped bright
all new Lower Rigging, and the Masts & Spars
all overhauled.*

The Surveyor to state the present Condition of	
Upper Deck Fastenings	<u>Good</u>
Spirkettling	<u>4</u>
Plank Shears	<u>4</u>
Topsides	<u>4</u>
Upper Deck with its Appendages	<u>4</u>
Lower Deck Fastenings	<u>4</u>
Wales	<u>Good</u>
Counter	<u>Good</u>
Plank and Treenails (Outside to the Water's Edge.)	<u>to the keel good</u>
Rudder	<u>Good</u>
Windlass	<u>Good</u>
Capstan	<u>Good</u>

General Observations and Opinion, *The appearance of this ship is very good
as required by the Instructions, throughout and in my opinion she is fully
admitted to remain in her present class 12A1*

The Amount of Fee.....£ 3 : 3 : - is received by me.

Committee Minute 22 July 1836

Character assigned Record Copper & Continued Class 12A1



© 2019

Lloyd's Register
Foundation

6170-665 Not