

REPORT of SURVEY for REPAIRS.

No. 2650 Port of London Date April 15th 1836
~~312~~ 204
 Survey of the Brig Richmond Hill Master B. Forest
 Tonnage 235 By whom built _____ Where built St John N.B.
 When built 1028 Owners Davidson Barclay Port belonging to London
 Destined Voyage Bertice
 Surveyed Afloat or in Dry Dock in the dry dock

Original Survey, No. 312 Dated 1834 & 1835 Classed B.1
 Port of London

Repairs. At the present time has been sheathed with inch boards over felt & coppered, two planks shifted below the counter, and caulked from the keel upwards, treenails overhauled, and a general examination

I concur in the recommendation above having seen this vessel during the repair J. Hayley

General Observations
 and Opinion, as
 required by the
 Instructions


The timbers where exposed were quite sound; has no appearance of working at the beam ends, and is in a good state of repair & efficiency and I am of opinion is fit for the safe conveyance of dry and perishable cargoes. Middleton

The Amount of Fee.....£ 1 : 1 : 0 is received by me. at the Office

Committee Minute 22 July 1836

Character assigned

Record Repairs & continue Chap R.1



© 2019

Lloyd's Register
 Foundation

0570-1665 NO 1
 LON 599-0430