

ANNUAL SURVEYS.

2684

No. 2686 Survey held at London Date August 13th 1836
 on the Bk Fortune Master J. Lister
 Tonnage 341 Built at Quebec When built 1825
 By whom built _____ Owners Lister & Co
 Port belonging to Glasgow Destined Voyage New South Wales
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 638 Port of London 1834 Classed "A, 1"

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings <u>Good & firm</u>	Transoms <u>ditto</u>	Pumps _____
Lower Deck Beams & Fastenings <u>ditto</u>	Timbers of the Frame <u>sound where seen</u>	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Well found</u>
Plank Shears <u>ditto</u>	Wales <u>ditto</u>	Cables <u>ditto</u>
Waterways <u>ditto</u>	Plank and Treenails <u>ditto</u> (Outside to the Water's Edge)	Anchors <u>ditto</u>
Hatchway Comings <u>ditto</u>	Rudder <u>ditto</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>ditto</u>	

General Observations and Opinion, The appearance of this vessel is favorable no symptoms of
 as required by the Instructions, waking at the beam ends, or decay, has not been in the dry docks
therefore cannot give the state of the bottom, caulked above the
keel in 1835; I am of opinion she may remain in her present class

Committee Minute 9 August 1836

Character assigned Continued Class A, 1
Middleton

No. 228 Survey held at London Date August 13th 1836
 on the Bk The Master C. Robson
 Tonnage 241 Built at Sunderland When built 1826
 By whom built _____ Owners Robson & Co
 Port belonging to London Destined Voyage Constantinople
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 369 Port of London 1834 Classed "A, 1"

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms <u>ditto</u>	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame <u>sound where seen</u>	Masts, Yards, &c. _____
Spirkettling _____	Topsides _____	Sails <u>Well found</u>
Plank Shears _____	Wales _____	Cables <u>ditto</u>
Waterways _____	Plank & Treenails _____ (Outside to the Water's Edge)	Anchors <u>ditto</u>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging <u>Good</u>
	Windlass _____	

General Observations and Opinion, Caulked in December 1835, is at the present time in very good
 as required by the Instructions, condition both as regards the hull & stores and may continue
her present class

Committee Minute 9 August 1836

Character assigned Continued Class A, 1
Middleton



© 2019

Lloyd's Register
Foundation

970-6656
LON