

2819 *Lon*

No. _____ Survey held at *London* Date *3 Oct* 18 *86*
 on the *Resource* Master _____
 Tonnage *417* Built at *Calcutta* When built *1805*
 By whom built _____ Owners *J Ward*
 Port belonging to *London* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *London Dock*

Original Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan <i>good</i>
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps <i>2 iron Pumps</i>
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <i>tick your good</i>
Spirkettling _____	Topsides _____	Sails <i>are on shore not seen</i>
Plank Shears _____	Wales _____	Cables <i>about 20 fathoms. Sufficient in length</i>
Waterways _____	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of <i>3 iron. Iron. These want</i>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging <i>New</i>
	Windlass _____	Copper _____

General Observations and Opinion, *to complete her stores she requires an 8 1/2 inch*
 as required by the Instructions, *Steam Hammer & Pump, & Steam Whistle Anchor*
which it is supposed will be supplied, no one, or some to give
power to.

Committee Minute _____ 183

Character assigned _____

Handwritten signature



Lloyd's Register
Foundation