

REPORT of SURVEY for REPAIRS.

No. 2224 Survey held at London Date Oct 26 1836
on the Ship Catherine Master Rose
Tonnage 522 Built at London When built 1819
By whom built Green & Co Owners B Tenn
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Messrs Greens Dry Dock

Original Survey, No. 2228 1713 Dated 1835 Chased No 1
Port London

Repairs. *At the present time Wood sheathing repaired & caulked. Boodings & Hull seams listed and caulked. Topsides overhauled & caulked several pieces put in - & the Bottom recopied*

The Surveyor to state the present Condition of
Upper Deck Fastenings Fair condition
Spirketting _____
Plank Shears _____
Topsides Indifferent about the fastenings
Upper Deck with its Appendages Good
Lower Deck Fastenings Do

Wales Good
Counter _____
Plank and Treenails _____
(Outside to the Water's Edge)
Rudder _____
Windlass _____
Capstan _____

General Observations and Opinion, *When this ship was first docked I recommended the*
as required by the Instructions, *owner to give her new Topsides or at least to shift all the*
defective planks - this he has declined doing - In other respects
she is in fair condition George Bayley

The Amount of Fee..... £ 3 : 3 : 0 is received by me. at the Office

Committee Minute 11 November 1836

Character assigned Reduce to F, 1 & give notice to the owner
Messrs.