

ANNUAL SURVEYS.

3085

No. 3085 Survey held at London Date January 21 1837
 on the Schooner Cumanus Master Werner
 Tonnage 72 Built at Yarmouth When built 1834
 By whom built _____ Owners Williams
 Port belonging to Swansea Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Walton's Quay

Original Survey, No. 2319 Port of London 1835 Classed 9 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <u>Good</u>
Spirkettling _____	Topsides <u>Good</u>	Sails _____
Plank Shears <u>Good</u>	Wales _____	Cables _____
Waterways _____	Plank and Treenails (Outside to the Water's Edge) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>Single</u>

General Observations and Opinion, as required by the Instructions, Caulked from Keel up and is now in good and efficient condition
George Bayley

Committee Minute 31 Jan 1837
 Character assigned Class A 1 in 9 years
G. B.

No. 834 Survey held at London Date January 23 1837
 on the Barque Medora Master Coward
 Tonnage 235 Built at Bristol When built 1825
 By whom built _____ Owners Alfred & Co N Donnell
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Curling Ho Dry Dock

Original Survey, No. 970 & 1664 Port of London 1835 Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>Good fair</u>	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. _____
Spirkettling _____	Topsides _____	Sails <u>Good</u>
Plank Shears <u>Condition</u>	Wales _____	Cables _____
Waterways _____	Plank & Treenails (Outside to the Water's Edge) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>ref present time good</u>

General Observations and Opinion, as required by the Instructions, At the present time an additional pair of Iron Hanging Knees - to Hold Beams - she is in my opinion eligible to remain classed A. 1
George Bayley

Committee Minute 31 Jan 1837
 Character assigned Class A. 1
G. B.

Fee £ 1. 1. 0 Received by me W. B.
 March 31st 1837

Lloyd's Register
 Foundation