

REPORT of SURVEY for REPAIRS.

No. 3899 Survey held at London Date March 8 1837
 on the Brig Ocean Master J. Fell
 Tonnage 285 Built at Garnon When built 1832
 By whom built _____ Owners J. Fell
 Port belonging to London Destined Voyage Guiana
 If Surveyed Afloat or in Dry Dock Chew Lane Dock

Original Survey, No. 666, 1587 & 2776 Dated 1834 Classed 10 A 1
 Port London July — 1836

Repairs. *At the present time stripped - caulked from keel up ship being & keel seam caulked - 3 pair of Iron Hanging knees to Hold beams put in - thoroughly overhauled and recoppered on deck*

See Certificate at the back

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treennails _____
 (Outside to the Water's Edge)
 Rudder _____
 Windlass _____
 Capstan _____

General Observations and Opinion,
 as required by the Instructions,

*Shast Rigging Hails good etc.
 This vessel presents a fair and substantial appearance and is in my opinion entitled to remain classed 10 A 1*

George Baileys

The Amount of Fee..... £ 1 : 1 : 0 is received by me.

*Genl Commr Apr 27 1837
 "Raised to 11 Years"*

Committee Minute 17 March 1837

Character assigned Class 10 A 1