

ANNUAL SURVEYS.

3347

No. 3347 Survey held at London Date May 4 1837
 on the Bark Augusta Master Edenborough
 Tonnage 385 Built at Lundelund When built 1834
 By whom built _____ Owners Steed
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackwall Dock

Original Survey, No. 2 Port of London 1834 Classed 1A1
 No. 2214 " " London 1834

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|---|----------------------------|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirkettling | Topsides | Sails |
| Plank Shears | Wales | Cables |
| Waterways | Plank & Treennails (Outside to the Water's Edge) | Anchors No. of |
| Hatchway Comings | Rudder | Standing & Running Rigging |
| | Windlass | Copper |

General Observations and Opinion, At the present time caulking from the ~~last~~ Copper
 as required by the Instructions up - and presents throughout a fine appearance
she is in my opinion entitled to remain in her present
cap 1A1

Committee Minute May 1837 George Bauley
 Character assigned 1A1 LB

No. 347 Survey held at London Date May 4 1837
 on the Bark Whitty Master Swinton
 Tonnage 347 Built at Whitty When built 1837
 By whom built H & G Barnett Owners Chapman & Co
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Pateliff Dry Dock

Original Survey, No. 63 Port of Whitty 1837 Classed 1A1

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|---|----------------------------|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirkettling | Topsides | Sails |
| Plank Shears | Wales | Cables |
| Waterways | Plank & Treennails (Outside to the Water's Edge) | Anchors No. of |
| Hatchway Comings | Rudder | Standing & Running Rigging |
| | Windlass | Copper |

General Observations and Opinion, At the present time Bottom caulked & appear
 as required by the Instructions to the water - she is in my opinion well entitled
to her present cap 1A1

Committee Minute May 1837 George Bauley
 Character assigned 1A1 LB