

# ANNUAL SURVEYS.

3383

No. 3383 Survey held at London Date May 15<sup>th</sup> 1837  
 on the Brig Indian Chief Master Hart  
 Tonnage 210 Built at St. Andrew When built 1830  
 By whom built \_\_\_\_\_ Owners C. F. Barry  
 Port belonging to London Destined Voyage Archangel  
 If Surveyed Afloat or in Dry Dock As the Vessel

Original Survey, No. 541 Port of London 1834. Classed 5 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings <u>do</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>do</u>	Timbers of the Frame _____	Masts, Yards, &c. <u>Good</u>
Spirketting <u>do</u>	Topsides _____	Sails <u>Carehauled</u>
Plank Shears <u>Sufficient in place</u>	Wales _____	Cables _____
Waterways _____	Plank & Treennails (Outside to the Water's Edge) _____	Anchors No. of _____
Hatchway Comings <u>Good</u>	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>As the Vessel</u>

General Observations and Opinion, At the present time called from the keel up - The Planking  
as required by the Instructions,  
the Planking of the Bottom & upper works from throughports and bulk for the  
most safe defective and Sufficient state of the Plank sheers should recommend her remaining  
of the ten tenths 1/3 Sufficient.

Committee Minute 20 June 1837

Character assigned

Comm. Minute 22 June 1837 George Bayley 2 Lines  
Character assigned in the State of the Plank sheers  
as required by the Instructions, when the vessel was  
was Owner, 16 June 1837

No. 1066 Survey held at London Date May 15<sup>th</sup> 1837  
 on the Schooner Monkey Master Brigitt  
 Tonnage 114 Built at Hastings When built 1831  
 By whom built \_\_\_\_\_ Owners J. J. Adam  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock As the Vessel

Original Survey, No. 317 Port of London 1834. Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps <u>Good</u>
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <u>As the Vessel</u>
Spirketting <u>Good</u>	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank & Treennails (Outside to the Water's Edge) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>As the Vessel</u>

General Observations and Opinion, The general appearance of this vessel is fine and good  
as required by the Instructions, 8 in my opinion should remain classed 12 A 1

Committee Minute 2 June 1837

Character assigned

12 A 1 George Bayley  
as required by the Instructions,