

ANNUAL SURVEYS.

3393

No. 215 Survey held at London Date June 3rd 1837
 on the By Broadbalt Master Morris
 Tonnage 796 Built at Shirburn When built 1823
 By whom built Owners
 Port belonging to London Destined Voyage East
 If Surveyed Afloat or in Dry Dock on the Ways

Original Survey, No. 1288 Port of London Classed A, 1

The Surveyor is required to state the present Condition of the

Decks <u>Indifferent</u>	Breasthooks <u> </u>	Capstan <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Transoms <u> </u>	Pumps <u> </u>
Lower Deck Beams & Fastenings <u>Defective</u>	Timbers of the Frame <u> </u>	Masts, Yards, &c. <u> </u>
Spirkettling <u> </u>	Topsides <u> </u>	Sails <u> </u>
Plank Shears <u> </u>	Wales <u> </u>	Cables <u> </u>
Waterways <u> </u>	Plank and Treennails <u> </u>	Anchors No. of <u> </u>
Hatchway Comings <u> </u>	(Outside to the Water's Edge) Rudder <u> </u>	Standing & Running Rigging <u> </u>
	Windlass <u> </u>	Copper <u> </u>

General Observations and Opinion, The above vessel wants repairs the bottom not having been
 as required by the Instructions, caulked since 1827, three or four planks of the Sheathing
have been taken off in midships and the treennails bored out
which were quite decayed & the upper & side beams work very
rapidly.

Committee Minute June 1837
 Character assigned Efficient Character & heavy Whidston
Wants repairs for bottom & planks

No. 216 Survey held at London Date June 5th 1837
 on the Little Hittipin Master Sam
 Tonnage 76 Built at Blythe When built 1814
 By whom built Owners
 Port belonging to Blythe Destined Voyage Holland
 If Surveyed Afloat or in Dry Dock on the Ways

Original Survey, No. 1346 Port of London Classed A, 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u> </u>	Capstan <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Transoms <u> </u>	Pumps <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Timbers of the Frame <u> </u>	Masts, Yards, &c. <u> </u>
Spirkettling <u> </u>	Topsides <u> </u>	Sails <u> </u>
Plank Shears <u> </u>	Wales <u> </u>	Cables <u> </u>
Waterways <u> </u>	Plank & Treennails <u> </u>	Anchors No. of <u> </u>
Hatchway Comings <u> </u>	(Outside to the Water's Edge) Rudder <u> </u>	Standing & Running Rigging <u> </u>
	Windlass <u> </u>	Copper <u> </u>

General Observations and Opinion, Very good condition & Sam. of opinion is fit for the
 as required by the Instructions, safe conveyance of dry & perishable cargoes

Committee Minute June 1837
 Character assigned A, 1 Whidston