

ANNUAL SURVEYS.

3421

No. 3421 Survey held at London Date May 31 1837
 on the Ship Atlas Master Humb
 Tonnage 412 Built at London When built 1820
 By whom built _____ Owners Chalmers
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Pictou Dock & W. J. Dock

Original Survey, No. 16182618 Port of London 1835 Classed Letter A 6 Years

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treennails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>Good</u>

General Observations and Opinion, The vessel is in good and efficient condition
 as required by the Instructions, in my opinion should remain classed
Letter A for 6 years
George Bayley

Committee Minute 24 June 1837
 Character assigned C. A. 1
C. S.

No. _____ Survey held at London Date June 20th 1837
 on the Ship Sedition Master Garton
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners Garton
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Pictou Dock

Original Survey, No. _____ Port of London Fee not Paid Classed _____

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treennails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>Good</u>

General Observations and Opinion, At the present time is in good and efficient
 as required by the Instructions, condition in my opinion should be classed
Letter A for 6 years
George Bayley

Committee Minute _____ 1837
 Character assigned _____