

# ANNUAL SURVEYS.

3465

No. 3465 Survey held at London Date July 17<sup>th</sup> 1837  
 on the Bg. Suster Master Ramsay  
 Tonnage 1260 Built at Hull When built 1818  
 By whom built \_\_\_\_\_ Owners Fraser & Co.  
 Port belonging to London Destined Voyage Baltic  
 If Surveyed Afloat or in Dry Dock in the Dry Dock

Original Survey, No. 3465 Port of London

Classed A. 1

The Surveyor is required to state the present Condition of the

|   |  |                                 |
|---|--|---------------------------------|
| Decks <u>Good</u>                         | Breasthooks <u>Sound</u>                     | Capstan                         |
| Upper Deck Beams & Fastenings <u>Good</u> | Transoms <u>"</u>                            | Pumps                           |
| Lower Deck Beams & Fastenings <u>"</u>    | Timbers of the Frame <u>Sound where seen</u> | Masts, Yards, &c.               |
| Spirkettling                              | Topsides                                     | Sails <u>Good</u>               |
| Plank Shears <u>Good</u>                  | Wales  | Cables <u>"</u>                 |
| Waterways <u>Good</u>                     | Plank and Treennails <u>Good</u>             | Anchors No. of <u>will find</u> |
| Hatchway Comings                          | Rudder                                       | Standing & Running Rigging      |
|   | Windlass                                     | Copper                          |

General Observations and Opinion, At the present time eight new ledging oak beams  
 as required by the Instructions, to the old beams & bottom examined. Saw is a very  
efficient state & fit for the safe conveyance of dry &  
perishable cargoes

Committee Minute 10 July 1837

Character assigned A. 1

No. 236 Survey held at London Date July 17<sup>th</sup> 1837  
 on the Bg. Janet Master D. Batten  
 Tonnage 1230 Built at Alma When built 1825  
 By whom built \_\_\_\_\_ Owners Wingate & Co.  
 Port belonging to Alma Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 146 Port of \_\_\_\_\_

Classed A. 1

The Surveyor is required to state the present Condition of the

|   |                                  |                               |
|---|----------------------------------|-------------------------------|
| Decks                                     | Breasthooks                      | Capstan                       |
| Upper Deck Beams & Fastenings             | Transoms                         | Pumps                         |
| Lower Deck Beams & Fastenings <u>Good</u> | Timbers of the Frame             | Masts, Yards, &c. <u>Good</u> |
| Spirkettling                              | Topsides                         | Sails <u>"</u>                |
| Plank Shears <u>Sound</u>                 | Wales                            | Cables <u>will find</u>       |
| Waterways                                 | Plank and Treennails <u>Good</u> | Anchors No. of                |
| Hatchway Comings                          | Rudder                           | Standing & Running Rigging    |
|   | Windlass                         | Copper                        |

General Observations and Opinion, Has been on the ways & had the copper patched general  
 as required by the Instructions, appearance & is in an efficient state for the safe  
conveyance of dry & perishable cargoes

Committee Minute 10 July 1837

Character assigned A. 1