

3665

No. _____ Port of Sunderland Date 30th Apr 1834

Survey of the Barque Jane Lockhart Master J. Holford

Tonnage 250 Owners Wm. Delrymple Port belonging to Dominica

By whom built _____ Where built Sunderland When built 1828

Destined Voyage Dominica

Dimensions.				Thickness of Plank.	
Feet.		Inches.		Outside.	Inside.
Length of Keel		Depth of Hold		Bilge to Wales	Ceiling below Hold Beams
Rake of Stem		Lower Hold		Short Hoods	Clamps and Bilge Planks
D ^o of Stern Post		Between Decks		Bilge to Keel	Upper Deck Clamps and Spirketting
Extreme Breadth				Wales	Twist Deck Ceiling
				Topsides	
				Shear Strake	
				Plank Shears	

Scantling of Timber.				
	Inches.	Sided Inches.	Masked Inches.	Sort of Wood.
Timber and Space, each				
Floors in the middle				
_____ at the ends				
1 st Foothooks				
2 nd Foothooks				
3 rd Foothooks				
Top Timbers				
Deck Beams				
_____ Middle				
_____ at the Ends				
_____ Knees				
Hold Beams				
_____ Middle				
_____ at the Ends				
_____ Knees				
Main Kelson				
Scarphs of Kelson				

2 wood Tomes Sheppert Breast Hooks
We certify that the preceding is a correct description of the above-named Vessel. Witness hand, this _____ day of _____

Builder's Name _____

Surveyor's Name _____

Masts, Yards, &c.

	Quality of Wood.	Length, &c.
Bowsprit		
Foremast	<u>one superior</u>	
Main Mast	<u>superior</u>	
Mizen Mast	<u>good quality</u>	
<u>2 fore pumps</u>		

Sails.

No.		No.
	Fore Topmast Stay Sails	
	Fore Sail	
	Fore Topsails	
	Main Sails	
	Main Top Sails	
	And is generally well found in other sails. }	

Cables, Cordage, &c.

	Fathoms.	Inches.
Cables, Hemp		
D ^o Iron		
Hawser		
Towlines		
1 st Warp		
2 nd D ^o		

Anchor.

No.		No.	
	Bower		Number and Description.
	Stream		
	Kedge		

Standing and Running Rigging is all found to be sufficient in size, and good in quality. }

We certify that the preceding is a correct description of the Stores of the above-named Vessel.

Owner's Name _____

Nautical Surveyor's Name _____



SURVEYOR'S REMARKS.

Timbering. *is English Oak of good quality fairly squared*
 The Quality, *rather good workmanship*
 Squaring, and
 Workmanship.


Plankings: *is English Oak of good quality fairly wrought*
 Outside and Inside
 Quality, Edging,
 and Workmanship.

Fastenings. *are Copper, bolts bolted, is well fastened throughout*
 If Sheathed, *Part Sheathed with worn felt Hoguard 1832*
 Doubled, or
 Felted.

Repairs.

General Observations *This Ship when seen appears good sound*
and Opinion as *of missing workmanship had not worked*
required by the *as any other beam ends is fit for the conveyance*
Instructions. *of dry & perishable cargoes & should be classed as -*

R. Conway



© 2019

Surveyor Afloats—

The Amount of the Fee, £

is received by me.

Committee Minute

183

Character assigned

Lloyd's Register
Foundation