

REPORT of SURVEY for REPAIRS.

No. ³⁷⁵⁸₆₀₅ Survey held at Londen Date Nov 10th 18 37
 on the Blk Mary Bridgway Master G. Smith
 Tonnage 217 Built at Isle of Man When built 1834
 By whom built _____ Owners G. Smith
 Port belonging to Londen Destined Voyage Alexandria
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1353 Dated _____ 1836 Classed 7 A 2
 Port of Liverpool

Repairs In good condition

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of <u>3 Powers</u>
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

It is at the present time in a very high state of
efficiency both in the hull & stores & fully entitled
to be classed 7 A 1

The Amount of Fee.....£ / : / is received by me, G. Smith

Committee Minute 24 Dec 1837

Character assigned 7 A 1