

REPORT of SURVEY for REPAIRS.

No. 3815 Survey held at LONDON Date Dec^r 11th 1857
 on the Ship Ethelred Master Geo Whyte
 Tonnage 399 Built at LONDON When built 1811
 By whom built Wm Stair Owners J B Olofin
 Port belonging to LONDON Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Ceiling Dock during repair

Original Survey, No. 2030 Dated Dec 11 1855 Classed A. 1
 Port LONDON

Repairs

At the present time in consequence of having
 been ashore - shipped - several planks of the
 Ceiling shifted - Doubled with ^{3 in} Sautier Seal from
 the keel to the Wale upon Patent Chain wire and
 efficiently fastened - & recoppered as before -

When opened the Timbers of the Frame found
 in a sound and good condition -

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Trenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions.

In my opinion this ship is fit for the conveyance
 of dry and perishable Cargoes to and from all parts
 of the world and ought to be Classed A. 1

The Amount of Fee.....£ 2 : 2 : - is received by me Geo Whyte

Committee Minute 22 Dec 1857

Character assigned A. 1 Artwork