

ANNUAL SURVEYS.

No. 3824 Survey held at London Date Nov^r 1837
 on the Napoleon Master _____
 Tonnage 233 Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to Jersey Destined Voyage Vin (ing)
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, ~~to~~ Annexed Port of Report of former Survey, Classed _____

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of <u>2 B 14 16</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
as required by the Instructions,

*This vessel continues in good sound condition
fastenings firm and may be regarded as
recommended in former reports*

Committee Minute _____ 183

Character assigned _____

Lloyd's Register
Foundation