

LOAN602-00645

5824 Ton

Her Masts, Yards, &c. are in Good condition, and sufficient in size and length.

She has SAILS.		CABLES, &c.		ANCHORS.	
N ^o .		Fathoms.		Fathoms.	N ^o .
2	Fore Sails,	37 1/2	Chain	1 1/2	3
1	Fore Top Sails,	11	Hempen Stream Cable.....	6 1/2	2
2	Fore Topmast Stay Sails,	11	Hawser	6	1
1	Main Sails,	90	Towlines	4	
2	Main Top Sails,		Warp		
and		All of <u>Good</u> quality.		All of proper weight.	

Her Standing and Running Rigging is _____ sufficient in size and Good in quality.

She has One Long Boat and 2 others

The present state of the Windlass is Good Capstan _____ and Rudder Good

General Remarks—Statement and Date of Repairs.

The frame as far as it can be seen is of heavy Oak timber
Square of good quality. Planking foreign Oak of good
Quality well wrought

If Sheathed, Doubled, or Felted, Coppered
and Date when last done 1854

And Am of opinion this Vessel should be Classed 8 A 1

The Amount of the Fee..... £ 1 : 1 : 0 is received by me, 21/12/57
Perd by William E. Henderson

Committee Minute 22 Dec 1857

Character assigned A 1 per 8 Dec 1857

Ch

Lloyd's Register
Foundation