

ANNUAL SURVEYS.

7-3870

R

No. 2370 Survey held at LONDON Date 31st Jun^r 1888
 on the MS Proteclay Master Josson
 Tonnage 322 Built at London When built 1836
 By whom built _____ Owners W. & J. G.
 Port belonging to London Destined Voyage to Portugal
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 462 Port of LONDON Classed 1st A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchor's No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions, This Ship continues in good and efficient condition and may be continued as classed

Committee Minute 2 Feb^r 1838

Character assigned 1st A1

No. 237 Survey held at LONDON Date 31st Jun^r 1888
 on the Catherine & Elizabeth Master S. Morris
 Tonnage 329 Built at London When built 1833
 By whom built Wark Owners Long
 Port belonging to London Destined Voyage to Portugal
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. Q712703 Port of London Classed 1st A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchor's No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions, The condition throughout is good and efficient condition and may be continued as classed

Committee Minute 2 Feb^r 1838

Character assigned 1st A1