

ANNUAL SURVEYS.

3967

No. 3967 Survey held at London Date March 5th 1888
 on the Th. Penelope Master Lucy
 Tonnage 218 Built at Harwich When built 1818
 By whom built _____ Owners Th. Messier
 Port belonging to London Destined Voyage Malta
 If Surveyed Afloat or in Dry Dock in D. D.

Original Survey, No. 3018 Port of London Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>in good condition</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>in good condition</u>	Topsides _____	Sails _____
Plank Shears _____	Wales <u>in good condition</u>	Cables <u>in good condition</u>
Waterways _____	Plank & Treennails <u>in good condition</u> (Outside to the Water's Edge)	Anchors No. of <u>2</u>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, Is strong & substantial generally, decks & rigging
as required by the Instructions, good for the ensuing year, & the vessel
the convenience of any of her shareholders may be continued
as usual
 Committee Minute 16 March 1888
 Character assigned A. 1

No. 3968 Survey held at London Date March 1888
 on the Th. Foxhound Master Paton
 Tonnage 144 Built at Harwich When built 1836
 By whom built Paton Owners Paton
 Port belonging to Harwich Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in D. D.

Original Survey, No. 139 Port of Harwich Classed A. 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>in good condition</u>	Topsides _____	Sails <u>complete</u>
Plank Shears _____	Wales <u>in good condition</u>	Cables _____
Waterways _____	Plank & Treennails <u>in good condition</u> (Outside to the Water's Edge)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, She is strong well built vessel and in my opinion
as required by the Instructions, suitable to be continued as before
 Committee Minute 16 March 1888
 Character assigned A. 1

Lloyd's Register
Foundation