

ANNUAL SURVEYS.

3990
11/1

No. 3999 Survey held at London Date March 23rd 1890
on the By Salboden Master R. Monte
Tonnage 267 1/2 Built at Switzerland When built 1875
By whom built _____ Owners Hughes
Port belonging to Newcastle Destined Voyage Duckee
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 2522 & 2535 Port of London 1036 Classed A. 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>good</u>	Topsides	Sails <u>good</u>
Plank Shears	Wales <u>good</u>	Cables <u>good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <u>well found</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Even very good condition on appearance of working
as required by the Instructions, on Dec 23rd I am of opinion may retain her present shape
but the head Beam & Sides can't be

Committee Minute 24 March 1890

Character assigned A. 1

No. 308 Survey held at London Date March 23rd 1890
on the St. Ann's Master S. Morgan
Tonnage 36 1/2 Built at Whitby When built 1870
By whom built _____ Owners Chapman
Port belonging to Whitby Destined Voyage Duckee
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 303, 1120 Port of London 2140 & 3090 Classed A. 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame <u>good</u>	Masts, Yards, &c.
Spirkettling <u>good</u>	Topsides	Sails <u>good</u>
Plank Shears	Wales <u>sound</u>	Cables <u>good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <u>well found</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Her general appearance very favorable very firm as
as required by the Instructions, her fastenings and in good condition both as regards
the hull & Stow's Beam of opinion is fit for the safe
conveyance of cargo & her cargo may be

Committee Minute 20 March 1890

Character assigned A. 1