

4075

(Change of Owners)

# REPORT of SURVEY for REPAIRS.

No. 4075 Survey held at London Date April 14<sup>th</sup> 1830  
 on the R. S. *Nymph* Master J. Blin  
 Tonnage 123 Built at Leith When built 1826  
 By whom built \_\_\_\_\_ Owners J. Hill  
 Port belonging to West Coast Destined Voyage Home  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 2078 & 2079 Dated 1836 Classed A. 1  
 Port of London

Repairs In good condition

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>None found</u>
Plank Shears	Counter	Sails <u>found</u>
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of <u>1</u>
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion Is in a very efficient state for the safe conveyance of  
 as required by the Instructions Dry & punctual cargoes & may remain in her  
present state

The Amount of Fee.....£ : : is received by me,

Committee Minute 20 April 1830

Character assigned A. 1