

ANNUAL SURVEYS.

No. 4187 Survey held at London Date May 20th 1830
 on the Bo Concor Master Jas Smith
 Tonnage 100 Built at Harmonth When built 1837
 By whom built Tolliver Owners J D Palmer
 Port belonging to Harmonth Destined Voyage Buenos Ayres
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 150 Port of Harmonth Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables <u>260 fms 4 1/2 Chain</u>
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchors No. of <u>3 Bower 15 ton 18</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

Good *Good* *Good*

General Observations and Opinion. Seen a high state of efficiency and may be
 as required by the Instructions, raised to 12 A 1

Committee Minute 24 May 183

Character assigned 12 A 1

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treennails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

Committee Minute _____ 183

Character assigned _____