

ANNUAL SURVEYS.

4200

No. Survey held at London Date May 23rd 1828
 on the Rig Penona Master W. Kenney
 Tonnage 182 Built at Leith When built 1837
 By whom built Owners Bruce & Co
 Port belonging to Peterhead & Co Destined Voyage
 If Surveyed Afloat or in Dry Dock Peterhead & Co's wharf

Original Survey, No. 328 Port of Leith London 1077 1837 Classed SAI

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails <small>(Outside to the Water's Edge.)</small>	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, *When this vessel was upon Peterhead's wharf about 2 Months as required by the Instructions said a recommendation was given by me in some particulars which I was given to understand would be complied with as the vessel evidently required some critical fastening - No additional fastening*

Committee Minute 183 *has been put in to the present time*

Character assigned Delivered George Bayley
in 8 June & wasy

No. 766 Survey held at London Date May 23 1836
 on the Bank Violanus Master Wares
 Tonnage 317 Built at Swedish When built 1817
 By whom built Owners Hopper & Co
 Port belonging to London Destined Voyage Quebec
 If Surveyed Afloat or in Dry Dock Linkin's Dock

Original Survey, No. 341 Port of London June 1837 Classed A. 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails <small>(Outside to the Water's Edge.)</small>	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, *At the present time Copper stripped off and wood sheathing was examined & caulked from keel to wale - Mr. Courtenay having surveyed her last week when in the West India Dock, said not to go aboard*

Committee Minute 183 *George Bayley*
 Character assigned SAI *George Bayley*

LON602-0477