

# ANNUAL SURVEYS.

4288

No. 4288 Survey held at London Date July 3 1838  
 on the Schooner Tyro Master Tray  
 Tonnage 79 Built at PE Island When built 1824  
 By whom built \_\_\_\_\_ Owners Tray & Co  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock At Captain's ways

Original Survey, No. 1460, 3290 & 3336 Port of London Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings <u>4</u>	Transoms <u>4</u>	Pumps _____
Lower Deck Beams & Fastenings <u>4</u>	Timbers of the Frame <u>4</u>	Masts, Yards, &c. _____
Spirkettling <u>4</u>	Topsides <u>4</u>	Sails _____
Plank Shears <u>4</u>	Wales <u>4</u>	Cables _____
Waterways <u>4</u>	Plank and Treenails <u>4</u> (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings <u>1</u>	Rudder <u>4</u>	Standing & Running Rigging _____
	Windlass _____	Copper <u>Single</u>

General Observations and Opinion, At the present time the remaining portions of the Ceiling  
shifted and retrenched, new Carvel Batts and caulked  
from keel up - She is in my opinion entitled to remain  
classified A. 1  
George Dayley

Committee Minute 10 Aug 1838  
 Character assigned A. 1  
C. J.

No. 329 Survey held at London Date July 3 1838  
 on the Ship Duke of Argyll Master Bristow  
 Tonnage 629 Built at Newcastle When built 1833  
 By whom built Smith & Co Owners Smith & Co  
 Port belonging to London Destined Voyage At present at present  
 If Surveyed Afloat or in Dry Dock Ship - Fletchen Dry Dock

Original Survey, No. 388 & 1775 Port of London 1835 Classed 12 A. 1

The Surveyor is required to state the present Condition of the

Decks <u>caulked</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treenails _____ (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>Good</u>

General Observations and Opinion, In my opinion this ship is entitled to remain  
as at present classified 12 A. 1  
George Dayley

Committee Minute 10 Aug 1838  
 Character assigned 12 A. 1  
C. J.



© 2019

Lloyd's Register Foundation