

ANNUAL SURVEYS.

4364

No. 4364 Survey held at London Date August 3 1888
 on the Brig Windem Master Bowie
 Tonnage 158 Built at Southampton When built 1824
 By whom built _____ Owners St Griffiths
 Port belonging to London Destined Voyage Leghorn
 If Surveyed Afloat or in Dry Dock Mountain Dockways

Original Survey, No. _____ Port of London Classed _____

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings <u>New Arts</u>	Transoms <u>"</u>	Pumps _____
Lower Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. _____
Spirkettling _____	Topsides <u>2 Planks each side new</u>	Sails _____
Plank Shears <u>New</u>	Wales <u>Good</u>	Cables _____
Waterways <u>New</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings _____	Rudder <u>"</u>	Standing & Running Rigging _____
	Windlass <u>"</u>	Copper _____

General Observations and Opinion, At Leghorn new sheen Strakes &c as specified in the Certificate
 as required by the Instructions, forwarded by St Griffiths to the Office. The keel is straight and her
 form unaltered. The work done at Leghorn is efficiently performed
 & in my opinion she is now entitled to the favorable and consideration
 of the Committee

Committee Minute _____ 188

Character assigned _____

George Bayly
Surveyor to the Navy
London
 Lloyd's Register
 Foundation

LON603-0147