

REPORT of SURVEY for REPAIRS.

4365

Handwritten signature/initials

No. 4365 Survey held at London Date July 28 1838
 on the Bark Andromache Master Geo
 Tonnage 468 Built at Scarbro When built 1828
 By whom built _____ Owners Godwin & Lee
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Blackwall Dry Dock

Original Survey, No. 1768 & 3409 Dated 1835 Classed 10 A1
 Port London

Repairs *at the present time stopped. caulked from keel to water and resheathed with yellow metal to the water, and overhauled aloft*

By George Bayley

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *In my opinion this ship should remain as at present classed 10 A1*

George Bayley

The Amount of Fee.....£ 2 : 2 : - is received by me, *Geo*

Committee Minute 10 Aug 1838

Character assigned 10 A1 *used*