

ANNUAL SURVEYS.

4446

No. 4446 Survey held at London Date 29 Aug 1838
on the 13k Diana Master James Lamb
Tonnage 321 Built at Whitby When built 1824
By whom built — Owners Brathwaite
Port belonging to London Destined Voyage Bordeaux & Mauritius
If Surveyed Afloat or in Dry Dock Afloat & Howson's Slip

Original Survey, No. 1315, 3253 & 3748 Port of London Classed 10 A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
as required by the Instructions,

The greater part of the Black Stroke have
been now been shifted (with, fir) copper raised
a Stroke higher - continues in good and efficient
condition and may remain as clipped

Committee Minute

Character assigned

No. 493 Survey held at London Date 3 Sept 1838
on the Lucrilia Master James Lamb
Tonnage 372 Built at Southwick When built 1828
By whom built — Owners Hale & Co.
Port belonging to London Destined Voyage —
If Surveyed Afloat or in Dry Dock Atcham's Slip

Original Survey, No. 1736, 2300, 2815, 3246, 3658 & 3995 Port of London Classed 10 A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
as required by the Instructions,

Is in good condition and may continue
as clipped

Committee Minute

Character assigned



© 2019

Lloyd's Register
Foundation