

4576  
F.A.

# REPORT of SURVEY for REPAIRS.

No. 4576 Survey held at London Date 22<sup>nd</sup> Sep<sup>r</sup> 1838  
 on the Booth Master Craig  
 Tonnage 221 Built at Topham When built 1826  
 By whom built Wm & Co Owners Wm & Co  
 Port belonging to London Destined Voyage Granada  
 If Surveyed Afloat or in Dry Dock Curly's Dock

Original Survey, No. 507, 2393, 3396, 3707 & 4190 Dated \_\_\_\_\_ Classed \* A, 1  
 Port London

**Repairs** At the present time Shipped Caulked from the  
 keel to the waterway seam, generally overhauled and  
 recoppered on top.

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,  
 as required by the Instructions,

Continued in good condition fit for  
 the conveyance of any and perishable goods,  
 to & from all parts of the world and may  
 be continued as classed Continued

The Amount of Fee.....£ 1 : 1 : - is received by me, [Signature]

Committee Minute 23 Oct 1838

Character assigned A, 1 Antennae - recopd

