

REPORT of SURVEY for REPAIRS.

No. 4500 Survey held at London Date Oct 23rd 1838
 on the Bk. Sroughton Master W. Shennells
 Tonnage 202 Built at Shield When built 1826
 By whom built _____ Owners Coates
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock in the Dry Dock

Original Survey, No. 76 Dated 1837 Classed A 1
 Port of Newport

Repairs At the present time Coppered over paper to the eleven feet mark

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Is altogether in a very efficient state for the safe
 as required by the Instructions, conveyance of dry perishable cargoes to & from
all parts of the World and may continue in her
present shape

The Amount of Fee.....£ 1: 1: - is received by me, W. Shennells

Committee Minute 26th Oct 1838

Character assigned continue R. V. Asterisk record Copper