

ANNUAL SURVEYS.

4586

No. 4586 Survey held at London Date Oct 1838
 on the Ms Roberts Master Elder
 Tonnage 423 Built at Colchester When built 1815
 By whom built _____ Owners Elder
 Port belonging to London Destined Voyage Merous
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1149 Port of London Classed *A.1
12772-3690

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails <small>(Outside to the Water's Edge)</small>	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
as required by the Instructions,

She is in the most efficient condition and may be continued as classed

Committee Minute 26th Oct. 1838

Character assigned A.1 Asterisk

Continued

No. _____ Survey held at London Date Oct 1838
 on the Ms Beatrice Master Young
 Tonnage 278 Built at Isle of Man When built 1829
 By whom built _____ Owners Poppular
 Port belonging to London Destined Voyage Portsmouth
 If Surveyed Afloat or in Dry Dock Afloat & in Dock

Original Survey, No. 2915 Port of London Classed A.1
3379-4128

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails <small>(Outside to the Water's Edge)</small>	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
as required by the Instructions,

A hole cut out of the plank deck below the hole the timbers good there is in good condition & may be continued as classed

Committee Minute 26th Oct. 1838

Character assigned A.1

