

4592
LH

REPORT of SURVEY for REPAIRS.

No. 4592 Survey held at London Date Oct 19 1838
on the Black Tuscan Master L. Rene
Tonnage 181 Built at Poole When built 1831
By whom built _____ Owners Griffiths
Port belonging to London Destined Voyage Leghorn
If Surveyed Afloat or in Dry Dock Fountain Dock

Original Survey, No. 116983515 Dated 1834 Classed 12A1
Port London

Repairs

At the present time Stopped caulked from keel
to wale & recopied on top to 11.6. Topsides
caulked -

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
as required by the Instructions,

Presents a very firm and good appearance
throughout & in my opinion should remain
as claped

George Bayley

The Amount of Fee.....£ — : 10 : 6 is received by me, HS

Committee Minute 30th Oct 1838

Character assigned 12 D \ Record Copper

