

ANNUAL SURVEYS.

4598

No. 4598 Survey held at London Date Oct 24 1838
 on the Bar London Master Turner
 Tonnage 415 Built at London When built 1800
 By whom built _____ Owners J Grey
 Port belonging to London Destined Voyage Samaria
 If Surveyed Afloat or in Dry Dock Mr Snooks Dry Dock

Original Survey, No. 621, 1762, 2775 & 3656 Port of London Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Transoms <u>Good</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Spirketting <u>Good</u>	Topsides <u>Good</u>	Sails <u>Good</u>
Plank Shears <u>Good</u>	Wales <u>Good</u>	Cables <u>Good</u>
Waterways <u>Good</u>	Plank and Treenails <u>Good</u> (Outside to the Water's Edge)	Anchors No. of <u>Good</u>
Hatchway Comings <u>Good</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>Good</u>	Copper <u>Good</u>

General Observations and Opinion,

as required by the Instructions, at the present time all the Bolts in the keel, additionally
bolts, 2 pair Staple standards, 2 pair in amidships, 2
additional Bolts in each Flank of keel (4 in all) Rods
caulked tight, Stem rebolts, Upper piece of Stern Post shifted
This is in good order to remain as
at present clasped

Committee Minute 30th Oct. 1838

Character assigned A. 1

George Bayley

No. 337 Survey held at London Date October 26 1838
 on the Bar Charles Bowdler Master Bell
 Tonnage 290 Built at Chelmsford When built 1825
 By whom built _____ Owners Smith & Co
 Port belonging to London Destined Voyage St Vincent
 If Surveyed Afloat or in Dry Dock Chelmsford Dock

Original Survey, No. 180, 1849, 3423 & 3712 Port of London Classed A. 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <u>Broken & Wrecked</u>
Spirketting _____	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank & Treenails _____ (Outside to the Water's Edge)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>Good</u>

General Observations and Opinion,

as required by the Instructions, The appearance of this Ship is favorable
in my opinion she is eligible to remain
as at present clasped

Committee Minute 30th Oct. 1838

Character assigned A. 1

George Bayley