

REPORT of SURVEY for REPAIRS.

4625

LL

No. 4625 Survey held at London Date Oct^r 26 1836
 on the Brij Galeroid Master Stone
 Tonnage 270 Built at Bermuda When built 1826
 By whom built _____ Owners Stone
 Port belonging to St Vincent Destined Voyage St Vincent
 If Surveyed Afloat or in Dry Dock Dowson Dock

Original Survey, No. _____ Dated Nov^r 1837 Classed A. 1
 Port London

Repairs

At the present time Shipped, carried from the keel up & reappeared upon surface & generally overhauled

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

Good *Good* *Good & efficient*

General Observations and Opinion,
 as required by the Instructions,

In my opinion this vessel is fully entitled to her present Class A. 1

George Bayley

The Amount of Fee.....£ 1 : 1 : - is received by me, *attested*

Committee Minute 9 Nov^r 1838

Character assigned A. 1 record Copper

