

REPORT of SURVEY for REPAIRS.

No. 4645 Survey held at London Date Apr 2 1838
 on the Sark Emilie Master Pettingill
 Tonnage 294 Built at Novascotia When built 1835
 By whom built _____ Owners C Walton
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Mr^r Cowsons Dry Dock

Original Survey, No. 2227 & 4260 Dated 1836 Classed 4 A 1
 Port London

Repairs at the present time ~~examine the hull~~
sheathed with Yellow Metal upon Selt to 11 ft bins
Bottom caulked in June last

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>Yct 1838</u>	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions, In my opinion this vessel is entitled to remain
as at present Classed 4 A 1

George Bayley

The Amount of Fee.....£ 1 : 1 : - is received by me, at office

Committee Minute 13th Nov. 1838

Character assigned 4 A 1 record Copper