

# REPORT of SURVEY for REPAIRS.

No. 4652 Survey held at London Date Aug 1838  
on the B3 Jack Master Duke  
Tonnage 252 Built at London When built 1832  
By whom built Snook Owners John Smith  
Port belonging to London Destined Voyage Africa  
If Surveyed Afloat or in Dry Dock Ship Yarding Dry Dock

Original Survey, ~~to~~ Annexed Dated 1834 & 1836 not Classed  
Port London

Repairs At the present time stopped, carried from  
keel up & recoppering to the wale  
sheets stopped & overhauling  
generally overhauled in the hull which is  
in good condition

George Bayley

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,  
required by the Instructions,

The Amount of Fee.....£ 1: 1: - is received by me, AT

Committee Minute 16th Nov 1838

Character assigned Δ 8 Years AT