

# ANNUAL SURVEYS.

4658

No. 4658 Survey held at London Date 12<sup>th</sup> Nov<sup>r</sup> 1838  
 on the Harriet Master Forman  
 Tonnage 226 Built at London When built 1824  
 By whom built          Owners Robert  
 Port belonging to London Destined Voyage America  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No.          Port of London Classed A:1

The Surveyor is required to state the present Condition of the

Decks <u>fair Condition</u>	Breasthooks <u>        </u>	Capstan <u>        </u>
Upper Deck Beams & Fastenings <u>firm</u>	Transoms <u>        </u>	Pumps <u>        </u>
Lower Deck Beams & Fastenings <u>fair</u>	Timbers of the Frame <u>        </u>	Masts, Yards, &c. <u>new masts</u>
Spirkettling <u>        </u>	Topsides <u>good</u>	Sails <u>        </u>
Plank Shears <u>        </u>	Wales <u>Condition</u>	Cables <u>good</u>
Waterways <u>good</u>	Plank and Treenails <u>        </u>	Anchors No. of <u>sufficient</u>
Hatchway Comings <u>Condition</u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>        </u>
	Rudder <u>        </u>	Copper <u>        </u>
	Windlass <u>        </u>	

General Observations and Opinion, new bolts in lower deck water way & knees  
 as required by the Instructions, some ke nails shifted & cutted from the copper  
up is in good Condition fit for the conveyance of dry  
and perishable Cargos & may  
 Committee Minute          1838 be continued as before  
 Character assigned See London Survey 4651 Continued

No. 327 Survey held at London Date 12<sup>th</sup> Nov<sup>r</sup> 1838  
 on the Ship London Master Kent  
 Tonnage 441 Built at London When built 1813  
 By whom built          Owners Jagon  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1700 & 2656 Port of          Classed A:1

The Surveyor is required to state the present Condition of the

Decks <u>good Condition</u>	Breasthooks <u>        </u>	Capstan <u>        </u>
Upper Deck Beams & Fastenings <u>        </u>	Transoms <u>        </u>	Pumps <u>        </u>
Lower Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame <u>        </u>	Masts, Yards, &c. <u>        </u>
Spirkettling <u>        </u>	Topsides <u>good</u>	Sails <u>sufficient</u>
Plank Shears <u>        </u>	Wales <u>Condition</u>	Cables <u>        </u>
Waterways <u>good</u>	Plank and Treenails <u>        </u>	Anchors No. of <u>good</u>
Hatchway Comings <u>        </u>	(Outside to the Water's Edge.)	Standing & Running Rigging <u>        </u>
	Rudder <u>        </u>	Copper <u>        </u>
	Windlass <u>        </u>	

General Observations and Opinion, she has three tiers of Beams the fastenings  
 as required by the Instructions, of which are firm, and she is in very desirable port in  
good fair Condition fit for the conveyance of dry & perishable  
 Committee Minute 16<sup>th</sup> Nov<sup>r</sup> 1838 Cargos & may be continued as  
 Character assigned A:1 before