

REPORT of SURVEY for REPAIRS.

No. ⁴⁸ 4877 Survey held at London Date January 25 1839
 on the Brig Narcissus Master Gurnie
 Tonnage 207 Built at Scarb When built 1836
 By whom built Findall Owners W Findall
 Port belonging to London Destined Voyage Ceylon
 If Surveyed Afloat or in Dry Dock Globe Dock

Original Survey, No. 18 Port of Scarbro' 2647 Dated 1836 Classed 11A1
 Port London

Repairs At the present time stopped. Cautioned from the
to take fresh air with yellow skint to 11 feet

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	<u>Good 11 ft 1839</u>	Standing & Running Rigging

General Observations and Opinion, There is not the best appearance of straining upon
as required by the Instructions the Butts & Fastenings of this vessel. her entire appearance
is very favorable & in my opinion she is eligible to
remain as at present Classed 11A1

George Bayley

The Amount of Fee.....£ 1 : 1 : - is received by me, HA

Committee Minute 5 Feb 1839

Character assigned 11A1 Used Y M Shackling