

# REPORT of SURVEY for REPAIRS.

5057.

Survey of Property,

No. 240 Survey held at London Date 25 March 1839  
 on the Sh. "Florence" Master A. Davis  
 Tonnage 179 Built at Farmouth When built 1829  
 By whom built - Owners J. Reid & Co.  
 Port belonging to London Destined Voyage Madagascar  
 If Surveyed Afloat or in Dry Dock, Afloat

Original Survey, No. 37 Dated - Classed 12. A 1  
 Port Exeter, & London 4175 & 4834.

## Repairs

*Additional iron knees to hold beams in consequence of their being 4 of them lowered down two feet to build large accommodations.*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling <u>As</u>	Wales <u>As</u>	Masts, Yards, &c.
Plank Shears <u>good</u>	Counter <u>good</u>	Sails <u>In good</u>
Waterways <u>Consider</u>	Plank and Treenails (Outside to the Water's Edge) <u>Condition</u>	Cables <u>Condition</u>
Hatchway Comings	Rudder	Anchors No. of <u>Sufficient</u>
Breasthooks	Copper	Standing & Running Rigging <u>Sufficient</u>

General Observations and Opinion,  
 as required by the Instructions,

*In shifting the beams lower down in the after hold the timbers from the main mast aft, where exposed and proved to be thoroughly square and perfectly sound, may be continued as before.*

The Amount of Fee.....£ 1 : 1 : - is received by me, W. H. Courtney

Committee Minute 26 March 1839

Character assigned 12 A 1



© 2019

Lloyd's Register  
 Foundation  
 LON604-0430