

ANNUAL SURVEYS.

5126

No. 62 Survey held at London Date April 9th 1839
 on the By Cameron Master Heriott
 Tonnage 220 Built at Wokington When built 1827
 By whom built _____ Owners Heriott & Co
 Port belonging to Wokington Destined Voyage Antigua
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1156 Port of Liverpool
1160 Port of Wokington 1830 Classed A, 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks _____	Capstan <u>Good</u>
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling _____	Topsides _____	Sails <u>Well found</u>
Plank Shears _____	Wales <u>Good</u>	Cables _____
Waterways _____	Plank and Treenails _____	Anchors No. of <u>2 Bowers 2 Kedges</u>
Hatchway Comings _____	(Outside to the Water's Edge)	Standing & Running Rigging _____
	Rudder _____	Copper _____
	Windlass _____	

General Observations and Opinion,
 as required by the Instructions,

This vessel is in a very efficient state and I am of opinion is fit for the safe conveyance of Dry Goods to the West Indies & from all parts of the World and I recommend her being raised to A with the Asterisk

Committee Minute 12 April 1839

Character assigned

A. 1 Asterisk

No. 233 Survey held at London Date April 9th 1839
 on the By William Barras Master J. Price
 Tonnage 272 Built at Shields When built 1834
 By whom built _____ Owners Marshall
 Port belonging to London Destined Voyage Port Philip N.S.W.
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 140 Port of Newcastle
287 Port of Bristol 1830 Classed 11A1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides _____	Sails _____
Plank Shears _____	Wales <u>Good</u>	Cables <u>Well found</u>
Waterways _____	Plank & Treenails _____	Anchors No. of _____
Hatchway Comings _____	(Outside to the Water's Edge)	Standing & Running Rigging _____
	Rudder _____	Copper _____
	Windlass _____	

General Observations and Opinion,
 as required by the Instructions,

Is in a very high state of efficiency both in the Hull & Masts and Decking her present Class

Committee Minute 12 April 1839

Character assigned

11 A 1



© 2019

Lloyd's Register Foundation

Lon 604-0503