

REPORT of SURVEY for REPAIRS.

No. 270 Survey held at LONDON Date March 27 1839
on the Ship Albion Master Kind
Tonnage 427 Built at Swansea When built 1813
By whom built Smith Owners Hall & Garet Ho
Port belonging to LONDON Destined Voyage General
If Surveyed Afloat or in Dry Dock Witcher Dock, repairing

Original Survey, No. 358, 1140 Dated March 1838 Classed F. 1
Port LONDON 2182, 3093, 4011

Repairs At the present time in consequence of having
been ashore, stripped - nearly all new keel -
a number of Treennails started, the fore foot cut
up forward - Caulked throughout, Planks, wood sheathing
recooped to 15 feet, and the damages repaired
opened at Ridge. Timber sound and unbroken

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, In my opinion this vessel is fully eligible to
as required by the Instructions, remain as at present Classed F. 1
George Bayley

The Amount of Fee.....£ 2 : 2 : — is received by me, HA

Committee Minute 23 April 1839

Character assigned F. 1 Edward Davis