

ANNUAL SURVEYS.

5204

No. 429 Survey held at London Date May 2 1839
 on the Ship Plantagenet Master Dornett
 Tonnage 687 Built at Newcastle When built 1838 March
 By whom built Smith Owners Smith
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Cup's Yard in Dry Dock

Original Survey, No. 830 Port of Newcastle May Classed 12 A D

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|--|----------------------------|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirkettling | Topsides | Sails |
| Plank Shears | Wales | Cables |
| Waterways | Plank and Treenails (Outside to the Water's Edge) | Anchors No. of |
| Hatchway Comings | Rudder | Standing & Running Rigging |
| | Windlass | Copper |

Good *Good* *Good and efficient*

General Observations and Opinion, *at the present time caulked from the Copper up*
 as required by the Instructions, *I & scum of the Deck next waterway*
the presents throughout a fair appearance - In
my opinion this is eligible to remain as classed 12 A 1

Committee Minute May 1839
 Character assigned 12 A 1 *George Bayley*

No. 429 Survey held at London Date May 2 1839
 on the Boat John Pink Master Nixon
 Tonnage 283 Built at London When built 1830
 By whom built Davidson Owners Davidson
 Port belonging to London Destined Voyage Lammermoor
 If Surveyed Afloat or in Dry Dock Cup's Yard in Dry Dock

Original Survey, No. 582, 2075 Port of London 1836 Classed 12 A 1

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|--|--|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. <i>unhailed 1839</i> |
| Spirkettling | Topsides | Sails |
| Plank Shears | Wales | Cables |
| Waterways | Plank & Treenails (Outside to the Water's Edge) | Anchors No. of |
| Hatchway Comings | Rudder | Standing & Running Rigging <i>unhailed</i> |
| | Windlass | Copper <i>good</i> |

Good *Good* *Good and efficient*

General Observations and Opinion, *at the present time a number of stanchions*
 as required by the Instructions, *shifted. caulked from the Copper up & unhailed*
aloft - This in my opinion entitled to remain
as classed 12 A 1

Committee Minute May 1839
 Character assigned 12 A 1 *George Bayley*

Special £ 2.2