

No. 5232

Survey held at London

Date June 20

1837

on the Bark Glenadale

Master Rasmusen

Tonnage 343

Built at P.R. Island

When built 1833 Oct

By whom built

Owners R. J. Smith &amp; Co

Port belonging to London

Destined Voyage

If Surveyed Afloat or in Dry Dock Burlington Dock

Original Survey, No.

Port of

Classed 4A1

The Surveyor is required to state the present Condition of the

Decks

Good

Breasthooks

Good. B.B.

Capstan

Upper Deck Beams &amp; Fastenings

Fir

Transoms

do do

Pumps

Lower Deck Beams &amp; Fastenings

do

Timbers of the Frame Good &amp; firm &amp; true

Masts, Yards, &amp;c.

Spirkettling

do

Topsides

Good

Sails

Plank Shears

Good - B.B.

Wales

do

Cables

Waterways

Fir. Good

Plank &amp; Treenails

do

Anchors No. of

Hatchway Comings

Good

Rudder

do

Standing &amp; Running Rigging

Windlass

do

Copper

Ref

General Observations and Opinion,



as required by the Instructions,

At the present time caulked from the Copper up and overhauled  
 presents a firm and substantial appearance & is in  
 my opinion entitled to be classed 4A1

Committee Minute

183

Character assigned

© 2019

Lloyd's Register  
Foundation